



Subsurface mooring and hardware
current (ADCP)
temperature



Figure 2-7g. Schematic of moorings at site HB08.